



TMW Systems, Inc.
 6085 Parkland Blvd.
 Mayfield Heights, OH 44124
 Tel: (440) 721-2020
 Fax: (216) 831-3606

Bill to: SPRINGHETTI GM, LLC.

Shipper: GENERAL MOTORS CORPORATION

2300 Hallock Young Rd Gate 12

Warren, OH 44481

Contact: 555-555-5555

**Bill of Lading
 Single Unit**

23536

Driver: Smith, Jim

Truck #: 125

Date: 7/17/20XX 3:35:05 PM

Consignee: SPGML

2501 DAVIDSON AVE

Cleveland, OH 44111


Contact:

YEAR	MAKE	MODEL	VIN	REMARKS
2018	CHEVY	CRUZE	1N1AB6AP8JC122811	

Automobiles are designed for road use and may acquire small scratches, scuffs, dents or abrasions. Carrier can not be liable for minor damage of this nature which is considered to be the result of natural wear and tear this inspection represents a general overall condition and is not all inclusive.

CHART OF IDENTIFICATION CODES

BB	Bent	L	Loose
BB	Buffer Burned	M	Missing
BR	Broken	P	Pitted
C	Cut	PC	Paint Chip
CR	Cracked	R	Rubbed
D	Dented	RU	Rusted
F	Faded	S	Scratched
FF	Foreign Fluids	SL	Soiled
G	Gouged	SS	Surface Scratch
T	Tons	ST	Stained



**ATTENTION CONSIGNEE,
 INSPECT YOUR VEHICLES(S) UPON DELIVERY!**

No claims for damages will be honored except as noted hereon at the time of delivery. Claims must be presented in writing within 24 hours.

Liability Disclaimer: It is agreed that Carrier is not lable for:

- A.** Damage caused by leaking fluids, battery acids, cooling systems, anti-freeze solution, industrial fallout of damage caused by acts of god or force majored.
- B.** Damage which is undetectable at time of pickup due to vehicles dirty condition, or weather condition.
- C.** Any glass Damage.
- D.** Mechanical or electrical functions and damages caused by ailing mechanics, electrical demise, exhaust asembly, alignment or suspension.
- E.** Under Carriage damage, and damage resulting from overloaded or lowered vehicles.
- F.** Shipper is responsible for perparing vehicle for shipment. Securing loose parts, mufflers or tail pipes, spoilers, non-stock kit additions, antennas, and switches. Any part that falls off during transport is the customer's responsibility, as are leaking fluids, including damages caused by said parts or fluids to any and all other vehicles involved. It is the customer's responsibility to notify carrier of any and all fluid leaks.
- G.** Any exhaust system, muffler or tail pipes, no exceptions.
- H. DAMAGED TO VEHICLES CAUSED BY:** a) Vehicle that cannot be driven on or off transport truck under its own power and / or b) Vehicle having defective or insufficient brake, parking brake, or parking gear.
- I.** Damaged caused by freezing of engine, or cooling system or batteries.
- J.** Damaged caused to vehicle from tie downs breaking or tearing.
- K.** Any convertible tops that are loose, torn or show extensive wear. Bras and or any type of canvas or material coverings.
- L.** The Carrier WILL NOT be responsible for damage NOT caused by the Driver.
- M.** The customer agrees that their vehicle is insured and their insurance has primary responsibility.

Vehicle Condition at Origin:

I have read, understand and agree to the terms and conditions set forth on the front and back of this form.

Signed:

Print Name:

Date: